

RIVER OBSTRUCTIONS

CREATED BY SUPER STORM SANDY, FALL 2012

PREPARED BY THE DEPARTMENT OF ENGINEERING SERVICES

11/6/2013



This document contains maps and photographs of tree obstructions in various locations throughout the Township caused by Super Storm Sandy in October of 2012. Locations listed herein obtained via roadside assessments and are high priority for removal. This document does not contain a complete list of locations of all waterway obstructions in the Township. This is for a grant application and is for informational purposes only.

Table of Contents

Table of Contents	2
MAP: Harrisons Brook Obstructions at Autumn Drive	3
Locations 1 & 2	3
MAP: Harrisons Brook Obstructions at Mt. Airy Road near Valley Road	4
Locations 3 & 4	4
MAP: Passaic River Obstructions at Kennedy-Martin-Stelle Farmstead	5
Locations 5-8	5
MAP: Passaic River Obstructions at Pond Hill Road	6
Locations 10-13	6
MAP: Harrisons Brook Obstructions at Mt. Airy Road near Newell Drive	7
Locations 14 & 15	7
FIGURE 1	8
FIGURE 2	8
FIGURE 3 & 4	9
FIGURE 5A	9
FIGURE 5B	10
FIGURE 6A	11
FIGURE 6B	11
FIGURE 7A	12
FIGURE 7B	12
FIGURE 8	13
FIGURE 9	13
FIGURE 10	14
FIGURE 11A	15
FIGURE 11B	15
FIGURE 12A	16
FIGURE 12B	16
FIGURE 12C	17
FIGURE 12D	18
FIGURE 13A	19
FIGURE 13B	19
FIGURE 13C	20
FIGURE 13D	20
FIGURE 14 & 15	21


HARRISONS BROOK OBSTRUCTIONS AT AUTUMN DRIVE






HARRISONS BROOK OBSTRUCTIONS AT MT. AIRY ROAD NEAR VALLEY ROAD






PASSAIC RIVER OBSTRUCTIONS AT KENNEDY-MARTIN-STELLE FARMSTEAD





PASSAIC RIVER OBSTRUCTIONS AT POND HILL ROAD





HARRISONS BROOK OBSTRUCTIONS AT MT. AIRY ROAD NEAR NEWELL DRIVE







FIGURE 1




FIGURE 2



FIGURE 3 & 4



FIGURE 5A




FIGURE 5B




FIGURE 6A



FIGURE 6B



FIGURE 7A



FIGURE 7B



FIGURE 8




FIGURE 9



FIGURE 10



FIGURE 11A



FIGURE 11B



FIGURE 12A




FIGURE 12B



FIGURE 12C



FIGURE 12D



FIGURE 13A



FIGURE 13B



FIGURE 13C



FIGURE 13D



FIGURE 14 & 15